



**BUILDINGS, SAFETY ENGINEERING  
AND ENVIRONMENTAL DEPARTMENT**

Coleman A. Young Municipal Center  
2 Woodward Avenue, Fourth Floor  
Detroit, Michigan 48226

Phone 313•224•2733 TTY:711  
Fax 313•224•1467  
[www.detroitmi.gov/BSEED](http://www.detroitmi.gov/BSEED)

March 7, 2025

HONORABLE CITY COUNCIL

**RE: RECOMMENDATION FOR DEFERRAL**

**ADDRESS: 3828 Courville**

**Owner: Detroit Rental Fund 6 LLC**

**Demolition Ordered: July 19, 2024**

In response to the request for a deferral of the demolition order on the property noted above, the Buildings, Safety Engineering and Environmental Department (BSEED) submits the following information:

A special inspection conducted on February 18, 2025, revealed that the building is secured and appears to be sound and repairable. The owner has paid all taxes and is current. The proposed use of the property is owner's use and occupancy. **This is the 1<sup>st</sup> deferral request for this property.**

**Therefore, we respectfully recommend that the demolition order be deferred for a period of six months subject to the following conditions:**

1. A permit for rehabilitation work shall be applied for within ten (10) business days from the date of the City Council decision.
2. BSEED will schedule a Progress Inspection within forty-five (45) calendar days from the date of the rehabilitation permit to determine whether substantial progress has been made. Thereafter, the owner must submit to BSEED detailed inspection reports, with photos showing evidence of the work completed, every forty-five (45) calendar days, for the duration of the rehabilitation work, to demonstrate that substantial progress has been made during the approved time frame for rehabilitation.
3. The building shall have all imminently hazardous conditions immediately corrected, be maintained, and securely barricaded until rehabilitation is complete. Rehabilitation work is to be completed within six (6) months, at which time the owner will obtain one of the following from this department:
  - Certificate of Acceptance related to building permits
  - Certificate of Approval as a result of a Housing Inspection
  - Certificate of Compliance, required for all rental properties
4. The owner shall not occupy or allow occupancy of the structure without a certificate (as outlined above).





5. **The yards shall be maintained clear of overgrown vegetation, weeds, junk and debris at all times.**
6. **Prior to seeking a permit extension, the owner must contact BSEED and request to extend the deferral period.**

We recommend that utility disconnect actions cease to allow the progress of the rehabilitation.

At the end of the deferral period, the owner must contact this department to arrange an inspection to evidence that conditions of the deferral have been satisfied and that there has been substantial progress toward rehabilitation. If the building becomes open to trespass or if conditions of the deferral are not followed, the deferral may be rescinded by the City Council at any time and we may proceed with demolition without further notice. In addition, pursuant to the Property Maintenance Code we will issue a Blight Violation Notice.

Any request exceeding three (3) deferrals must be made by petition to City Council through the office of the City Clerk.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Arthur Rushin".

Arthur Rushin  
Chief Enforcement Officer  
Property Maintenance

AR:sl

Cc: Detroit Rental Fund 6 LLC Dheeraj Varughese 23875 Michigan Ave Suite 539  
Dearborn MI 48124  
[DJ@NESSVSA.COM](mailto:DJ@NESSVSA.COM)



DNG2024-00092

Update    Reset    View Log    Reports    Help

Record #

[DNG2024-00092](#)

Unit Nbr

Floor

Address

3828 COURVILLE, DETROIT, MI 48224

Created By ACA

No

Inspection Type \*

Dang Bldg Deferral Inspection

Request Date

02/11/2025

Inspection Contact Name

Request Comment

approve or deny application

Contact Phone Number

Scheduled Date \*

02/12/2025

Scheduled Start Time

: AM

Inspector \* [Current User](#)

Christopher Binder

Department \* [Current Department](#)

DNG - Dangerous Bldg Inspector

Inspection Date

02/18/2025

Status \*

Vacant And Secure

Record Comments

Result Comment [Standard Comments](#)

2 story 1 family brick dwelling. Fire damaged. Vacant and secure. Yard maintained/rear fenced and inaccessible. ODM 7/15/2024. Rec approve deferral.

[check spelling](#)

Inspection Sequence Number

32979822



**3828 Courville**

